




- The stepper motor can make 24 steps in a full turn ; 15° per step.
See next page.


with a positive pulse on A, N1 will align there. Next, with a negative pulse on B, S2 will align there. Next, with a positive pulse on C, N3 will align there.





Cut out this part and with a pin-head connect it on top of part below

A



D

